08/10/24

Current / latest versions are at the top.

Gauge Models				
ULTRASONIC THICKNESS GAUGE MODEL: MS-SG SERIAL NO.				
V5.55 (M5-SG all models – Cygnus 2/3/4/5/6) Oct 2024				
 EE Measurement Mode updated and improved to decrease minimum thickness measurement range. B-Scan Issue with SE mode fixed 				
V5.51 (M5-SG all models – Cygnus 2/3/4/5/6) Apr 2023				
Fix for Bluetooth occasionally freezing when connection is closed				
V5.50 (M5-SG all models – Cygnus 2/3/4/5/6) Oct 2022				
Updated for T5BH Probe update.				
Fix for occasional datalo				
V5.47 (M5-SG all models – Cygnus 2/3/4/5/6) Aug 2022				
Fix for a Probe Detection issue found on V5.46				
V5.46 (M5-SG all models – Cygnus 2/3/4/5/6) Aug 2022				
Fix for B-Scans sometimes not saving to SD Card				
V5.43 (M5-SG all models - Cygnus 2/3/4/5/6) Jun 2022				
New release of M5-SG firmware				
Gauge Models				
Cygnus 2 ⁺ Cygnu Serial No.	Serial No. Cygnus 4 ⁺ Cygnus 5 ⁺ Cygnus 6 ⁺			
Cygnus 2	Cygnus 3 / 4 / 5 / 6			
V531-R966 (C2) Jun 2021	V531-R966 (C4/C6) V531-R968 (C3/C5) Jun 2021			
As C3/4/5/6 V5.31>	 Probe Zero method updated for new T5BH probes. Bug fix – Vibrate Alert when Auto Log enabled. 			
V530-R963 (C2) Feb 2021	V530-R963 (C4/C3/C6), V530-R964 (C3/C5) Feb 2021			

08/10/24

As C3/4/5/6 V5.30>	 Probe Zero method updated for new HT probes. ME Measurements updated for new S3C probes. Bug fix - Factory Menu - Sxx probe gain adjustment. Bug fix - gain boost when measuring plastics. C5+ Removed Manual Gain Mode in ME Measuring Mode.
V529-R960 (C2) June 2020 • As C3/4/6 V5.29>	V529-R960 (C3/C4/C6), V529-R961 (C3/C5 CN) June 2020 • Bugfix in Manual Gain Mode.
V528-R959 (C2) April 2020 • As C3/4/6 V5.28>	V528-R959 (C3/C4/C6), V528-R960 (C3/C5 CN) April 2020 Improvements to AutoGain in SE Mode. Improvements to EE Mode.
V526-R922 (C2) June 2019 • As C3/4/6 V5.26>	V526-R921 (C3/C4/C6 EN Only) June 2019 C3+ EN Gauge Added
V525-R913 (C2) February 2019 • As C3/4/5/6 V5.25>	V525-R911 (C4/C6), V525-R910 (C3/C5 CN) February 2019 SE Mode update. C5 fix for 'no probe files found' message
V524-R899 (C2) December 2018 • As C3/4/5/6 V5.24>	V524-R899 (C4/C6), V524-R900 (C3/C5) December 2018 • ME Mode – updated so S2C measures 250mm steel blocks stably.
	 V523-R891 (C4/C6) October 2018 Support for new Bluetooth module. High Temp Compensation now enables Manual Gain Mode. Maximum manual gain value is 58dB. 790 Probe profile revised.
V5.22-R876 August 2018 • As C3/4/5/6 V5.22>	V522-R880 (C4/C6) & V522-R881 (C3/C5) August 2018 • Fixed measurement issue with older T5B Probes (up to s/n 20370C) in SE Mode.
	V521-R876 (C6) & V521-R877 (C3) July 2018 • Fixed B-Scan Issue on Cygnus 6+ and Cygnus 3+ models.
V5.20-R874 June 2018	V5.20-R874 (C4, C6) & V5.20-R875 (C3, C5) June 2018

08/10/24

	 As C3/4/5/6 V5.20> Automatically supports LCD or OLED Display depending on hardware configuration. 	 Added Probe Gain Setting for T** probes when Single Point Calibration performed on Test Block (1/2" or 15mm). 		
	V5.18-R845 June 2017	V5.17-R845 June 2017		
	• As C4/6 V5.17>	 Changed ME Algorithm to remove occasional doubling and halving on heavy corrosion. Improved measurements through coatings. Data Logging fix for incorrect Radial Point names. Added High Temperature Compensation feature to Cygnus 4+ gauges. 		
		V5.16-R831 June 2017		
		B-Scan to CygLink : Fixed issue when sending more than 10 B-Scan files to CygLink.		
	V5.17-R756 March 2017	V5.15-R756 March 2017		
	• As Cygnus 4 V5.15>	Changed ME Algorithm to improve measurement performance and bring in line with Mk4 gauges.		
	V5.16-R745 February 2017	V5.14-R745 February 2017		
	• As Cygnus 4 V5.14>	Changed ME Algorithm to improve measurement performance on thinner corroded metal.		
	V5.15-R733 October 2016	V5.13-R735 October 2016		
Version & Details	• As Cygnus 4 V5.13>	 Probe Setups now loaded into the Gauge APD Detection method improved Prompts user to select probe when APD can't identify EE measurement improved Probe Zero measurement method improved Added T5BH probe to C6 gauge 		
		V5.12-R660 April 2016		
		 Added Two Point Cal. for ME Mode Added Update Rate option for T** Probes Added D790 Option in Probe Menu (C6+ only) Added Display Colour option added Enlarged A-Scan graph area Reduced power use and scan rate to 4Hz in ME mode 		
	V5.14-R649			

08/10/24

	F-1		
	February 2016		
	Update for SE Mode		
	V5.13-R638 January 2016 Fix for manual probe change in menu	-	-
	V5.12-R637 January 2016 Fix for not displaying gauge info on boot	-	-
	V5.11-R631 December 2015 • Fix for probe data transfer	V5.11-R633 December 2015 • Bluetooth Update	V5.11-R633 December 2015 • Bluetooth Update
	V5.10-R627 December 2015 • Min Measuring Range	V5.10-R627 December 2015 Min Measuring Range Data Logging on 4+ CygLink v5 Manual Gain on 4+	V5.10-R627 December 2015 Min Measuring Range Data Logging B-Scan CygLink v5
	V5.05-R517 June 2015 • General update.	V5.05-R513 June 2015 • General update.	V5.05-R513 June 2015 • General update.
	V5.04-R508 June 2015 • General update.	V5.04-R508 June 2015 • General update.	V5.04-R508 June 2015 • Manual Gain feature added. • General update.
	V5.03-R497 May 2015	V5.03-R497 May 2015	General update.
	Improvement to Echo-Echo Measurement.	Improvement to Echo-Echo Measurement.Minor fixes in Data Logging	
	V5.02-R488 May 2015 • First release	V5.02-R488 May 2015 • First release	
	• First release	First release	